

KEY: (1) Recommend evaluation by a structural engineer/geo-technical engineer (4) This item is a safety hazard - correction is needed
 (2) Recommended evaluation and repairs by a licensed contractor (5) Upgrades are recommended for safety enhancement
 (3) Refer to qualified termite report for further information * This item warrants attention/repair or monitoring

1 Driveway N/A Asphalt Concrete N/A

Appears serviceable Not Functional* Unsafe* Worn* Near end of lifespan* Not fully visible*
 Eroded Asphalt* Maintenance* Sealant needed* Deterioration* Evidence of poor drainage*
 No cracks found Common cracks Major cracks* Trip hazards* Surface raised* Surface settled*

Comments: The driveway appeared to be in serviceable condition at the time of the inspection.

2 Sidewalks N/A Concrete Brick Paver / Tile N/A

Appears serviceable Not Functional* Unsafe* Worn* Near end of lifespan* Not fully visible*
 No cracks found Common cracks Major cracks* Trip hazards* Surface raised* Surface settled*
 Concrete is above* Evidence of poor drainage* Other*

Comments: The sidewalk appeared to be in serviceable condition at the time of the inspection.

3 Retaining Walls N/A **LOCATION(S):** Concrete Stucco Block

Appears serviceable Not Functional* Unsafe* Worn* Near end of lifespan* Not fully visible*
 No cracks found Common cracks Major cracks (1) Moisture penetration* No drainage openings*

Comments:

4 Patio N/A **LOCATION(S):** West side Concrete Brick N/A

Appears serviceable Not Functional* Unsafe* Worn* Near end of lifespan* Not fully visible*
 No cracks found Common cracks Major cracks (1) Trip hazards* Surface raised* Surface settled*
 Concrete is above* Evidence of*

Comments: The patio appeared to be in serviceable condition at the time of the inspection.

5 Patio Cover N/A **LOCATION(S):** Earth contact (3)

Appears serviceable Not Functional* Unsafe* Worn* Near end of lifespan* Not fully visible*
 Attachment to house * Open Design Covered Roof (refer to Roof Page)*
 Moisture at Patio cover lacks Wood appears

Comments:

6 Decks / Porch N/A WOOD Waterproofed Coating Concrete N/A

LOCATION(S): A East Side B C

Appears Serviceable Not Functional* Unsafe* Worn* Near end of lifespan* Not fully visible*
 Deck is on grade--unable to inspect* Piers need Posts need
 Cracks Moisture Deck appears unsound (1) (2) (A) (B) (C)
 Flashing Earth-to-wood contact (3) (A) (B) (C)
 Porch* Steps* Wood steps, not fully supported Uneven*
 Screens* Panels* Unable to Railing of
 Railings are serviceable N/A Railing Railing of

Comments: The deck appeared to be in serviceable condition at the time of the inspection.

7 Fences & Gates N/A NOT INSPECTED Wood Chain Link N/A

Appears serviceable Not Functional* Unsafe* Worn* Near end of lifespan* Not fully visible*
 Posts are Blocks are Boards are
 No cracks Common cracks Major cracks (2) Fence height at
 Gate(s) need Self closing device is Post rusted & leaning*

Comments:

KEY: (1) Recommend evaluation by a structural engineer/geo-technical engineer (4) This item is a safety hazard - correction is needed
 (2) Recommended evaluation and repairs by a licensed contractor (5) Upgrades are recommended for safety enhancement
 (3) Refer to qualified termite report for further information * This item warrants attention/repair or monitoring

8 Exterior Stairs

N/A

Type: **Wood**

Location: **A West Side**

B

C

Appears serviceable Not Functional* Unsafe* Worn* Near end of lifespan* Not fully visible*
 Moisture Uneven N/A

Railings serviceable Railings Openings in rails too large (5)

Comments: The exterior stairs appeared to be in serviceable condition at the time of the inspection.

9 Exterior Walls

N/A

Structure: N/A

Wall Covering is: **Vinyl**

Appears serviceable Not Functional* Unsafe* Worn* Near end of lifespan* Not fully visible*
 No cracks found Common cracks* Major cracks (1) Cracks / openings need repair (2) Soil contact *(3)
 Moisture stains/damage* Damaged Nailing defects *

Comments: The exterior walls appeared to be in serviceable condition at the time of the inspection.

Notice: Wall insulation type and value is not verified* UFFI insulation or hazard are not identified* Conditions inside the wall cannot be judged* Lead paint testing is not performed*

10 Trim / Eaves,Fascia,Soffits

N/A

WOOD METAL VINYL N/A

Eaves, soffits, fascia & trim appears serviceable Not Functional* Unsafe* Worn* Near end of lifespan*
 Moisture stains at Not fully visible* N/A

Flashings / Trim : Not visible at:

Comments: The exterior trim appeared to be in serviceable condition at the time of the inspection.

11 Chimney(s)

N/A

Location: **A North Side**

B

C

D

Material: **A Metal** **B** **C** **D Concrete** **METAL FLUE** **WOOD FRAME**

Appears serviceable Not Functional* Unsafe* Worn* Near end of lifespan* Not fully visible*

Chimney / brick / mortar is: Settlement (2) Flashing is

Spark screen present Spark screen: Raincap / screen recommended *

Cracks/separations/sealing needed at Unlined flue (2) Cracks in chimney cap *

Ash dump / door is: Damage / deterioration / defect *

Comments: The chimney appeared to be in serviceable condition at the time of the inspection.

Notice: The interior of the flue was not inspected at this time. We recommend that you retain a qualified chimney sweep to clean and evaluate the flue *

12 Sprinklers

N/A

Not inspected* Non operational (2) Control box location

Appears serviceable Not Functional* Unsafe* Worn* Near end of lifespan* Not fully visible*

Valve Head Line Anti-siphon valves needed *

Adjust spray away from Areas of inadequate spray coverage * Adjust heads *

Comments:

Notice: Underground pipes cannot be judged for breaks or possible root intrusions. Association-maintained systems are not tested. Grove systems are not tested.*

13 Hose Faucets

N/A

Faucets are winterized and were not tested*

Appears serviceable Some inoperative / corroded (2) Leaks (2) Missing handle(s)* Broken handle(s)*

Comments:

14 Gutters & Downspouts

N/A

Full

Partial

None Installed

Appears serviceable Not Functional* Unsafe* Worn* Near end of lifespan* Not fully visible*

Drains blocked* Debris filled* Gutters / downspouts:

Add gutters & downspouts for drainage* Add splashblocks for drainage* Route downspouts away from building*

Roof / gutters not draining properly* No secondary drain(s) on roof (2) Subsurface drains not tested*

Comments: West side. Recommend gutter down spouts be routed away from the building for proper drainage.

Notice: Gutters and subsurface drains are not water tested for leakage or blockage.* Regular maintenance of drainage systems is required to avoid water problems at the roof and foundation.*

KEY: (1) Recommend evaluation by a structural engineer/geo-technical engineer (4) This item is a safety hazard - correction is needed
 (2) Recommended evaluation and repairs by a licensed contractor (5) Upgrades are recommended for safety enhancement
 (3) Refer to qualified termite report for further information * This item warrants attention/repair or monitoring

15 Grading N/A Level Site Slope Minor Moderate Steep (1) Stairstepped Banks

- Drainage of site/slope of soil at foundation is proper based upon visual observation Not fully visible*
- Improper soil slope toward foundation* Soil / pavement is high at foundation* Earth-to-wood contact visible* (3)
- Plants touch Trees planted close to structure *
- Surface drains noted, not tested - underground pipes cannot be judged* Overgrown landscaping*
- Signs of poor drainage / erosion*

Comments: Drainage of the site appeared to be in serviceable condition at the time of the inspection. Be careful of mounding mulch as to cause drainage towards foundation

Notice: This inspection does not include geological conditions or site stability information. For information concerning these conditions, a geologist or soils engineer should be consulted.

16 Slab-on-grade 17 Crawlspace 18 Basement N/A

- Foundation: Poured Concrete Masonry Block Brick Stone Piers Wood
- Columns: Concrete Steel Wood Masonry Block Brick Not Visible*
- Entered crawl space No access* Partial access* Viewed from access opening only*
- Door Cover : Damaged* Missing* Crawlspace Basement
- Foundations:** Visible Partially visible* Not visible at*
- Appears serviceable Not Functional* Unsafe* Worn* Near end of lifespan* Not fully visible*
- No cracks found N/A Further evaluation needed (1)
- No moisture present N/A Exposed footing*
- Unable to inspect
- Slab not visible due to
- Cracks Settlement

Ventilation: Serviceable N/A Vents

Comments: Crawl space is poured concrete sloping to sump pump.

Notice: All slabs experience some degree of cracking due to shrinkage in the drying process. In most instances floor coverings prevent recognition of cracks or settlement in all but the most severe cases. The inspector will, at additional cost, reinspect, provided the client removes floor covering and releases the inspector from damage caused by this process. Floor coverings are not removed during this inspection.*

- Floor Construction:** JOISTS TRUSSES CONCRETE NOT VISIBLE N/A
- Wood Frame:** N/A CONVENTIONAL WOOD FRAMING TRUSS Other
- Appears serviceable Not Functional* Unsafe* Worn* Near end of lifespan* Not fully visible*
- Framing is Missing framing Moisture
- Damaged Missing Earth-to-wood contact (2) (3)
- Joists Beams Post Columns Debris under house*
- Concrete floors: Evidence of
- Anchor bolts installed Shear panels
- Probing where deterioration is suspected revealed: Engineer recommended (1)
- Insulation fiberglass
- VAPOR RETARDER N/A Installed Not installed* Not visible* Loose* Installed incorrectly*
- Sump pump N/A Serviceable Not functional* Pump not tested* Sump pump needed*

Comments:

BASEMENT STAIRS N/A Serviceable Uneven rise(2)(4) Uneven run(2)(4) loose step(s) (2)(4)
 Railings Stairs too steep (2)(4)(5) Ceiling is

Comments:

Notice: The inspector does not determine the effectiveness of any system installed to control or remove suspected hazardous substances*
 No engineering is performed during this inspection *

KEY: (1) Recommend evaluation by a structural engineer/geo-technical engineer (4) This item is a safety hazard - correction is needed
 (2) Recommended evaluation and repairs by a licensed contractor (5) Upgrades are recommended for safety enhancement
 (3) Refer to qualified termite report for further information * This item warrants attention/repair or monitoring

Roof style: Main Roof Gable Sun Room Roof Gable Great Room Gable
How inspected: Walked Viewed from ladder* Viewed from ground* With binoculars* Inspection is limited*
 Not fully visible due to: Height Weather Snow Type Debris N/A

19 Main Roof N/A **Roof Covering is: Asphalt Composition Shingle # of layers: 1**
 Appears serviceable/within useful life Not Functional* Unsafe* Worn* Near end of lifespan*(2) Not fully visible
 Typical maintenance recommended. This usually consists of repair/replacement of damaged/missing ridge and other shakes/shingles. This maintenance should help ensure the water tightness of the building and be performed on a regular basis.*
 General condition favorable with signs of weathering and aging-regular maintenance and inspection advised.*
 Roof covering has Moisture stained / damage*
 Weathering* Aging* Burnt through (2) Cracking* Holes/opening (2) Exposed (2) Deteriorated membrane (2)
 Loose Displaced Damaged Missing: Pitch appears insufficient (2) Moss covered*
 Roof material appears to be improperly installed (2) Fasteners are (2)
 Roof appears to be Evidence of prior patching / repairs (2)
Comments: The main roof covering appears to be in serviceable condition.

20 Sun Room Roof N/A **Roof Covering is: Same as Main Roof # of layers: 1**
 Appears serviceable/within useful life Not Functional* Unsafe* Worn* Near end of lifespan*(2) Not fully visible*
Condition: Fasteners (2) Dented Rusted Deteriorated paint (2)
 Loose Displaced Damaged Missing Prior repairs (2) Insufficient Pitch(2) Moss covered*
 Roof material appears improperly installed (2) Holes/openings(2) Exposed(2) Deteriorated membrane(2)
Comments: The secondary roof covering appears to be in serviceable condition.

Notice: Roofs of this material are often not walked on to avoid causing damage. Not all tiles/slates are checked for attachment.* Inspection is limited*

21 Great Room Roof N/A **Roof Covering is: Same as Main Roof # of layers: 1**
 Appears serviceable/within useful life Not Functional* Unsafe* Worn* Near end of lifespan*(2) Not fully visible*
 Typical maintenance recommended. This usually consists of covering exposed/bare with additional coating/aggregate material. Repair of open seams, cracks in flashings, deteriorated roof coverings, etc. *
 Excessive damage (2) Excessive deterioration (2) Roof material appears to be improperly installed (2)
 Blistering* Cracking* Alligating* Open seams (2) Moss covered (2) Deteriorated surface (2)
 Evidence of Bare areas exposed to the sun (2) Fasteners
 Roof appears to be Evidence of prior patching / repairs (2)
Comments:

Roof Notes N/A **NOTICE: N/A**
Comments:

Notice: The report is an opinion of the general quality and condition of the roof.* The Inspector cannot, and does not, offer an opinion or warranty and to whether the roof has leaked in the past, or may be subject to future leakage. Notice: The report is an opinion of the general quality and condition of the roof.*

22 Exposed Flashings N/A **Flashings appears serviceable** N/A
 Not Functional* Unsafe* Worn* Near end of lifespan*(2) Not fully visible*
 Separation (s) / improper at: Roof* Wall* Drip edge* Vent Pipes* Skylight* Other *
 Vent caps appear serviceable Needs repair* Missing caps* Rusty flashing* Mastic covered*
 Damaged flashing* Improper flashing at: No visible flashing at:
 Skylight(s) appear serviceable Cracked (2) Damaged (2) Defect (2) Non professional skylight*
Comments: The exposed flashing appeared to be in serviceable condition.

Notice: Determining the presence of asbestos or hazardous materials is beyond the scope of this inspection.* Roofs, skylights and flashing are not water tested for leaks.* Notice: Tenting a home for fumigation may cause damage to roofs -- recommend reinspection for damage after tenting is completed.*

Page16 BATHROOMS

Report # : OTT 020404

KEY: (1) Recommend evaluation by a structural engineer/geo-technical engineer (4) This item is a safety hazard - correction is needed
 (2) Recommended evaluation and repairs by a licensed contractor (5) Upgrades are recommended for safety enhancement
 (3) Refer to qualified termite report for further information * This item warrants attention/repair or monitoring

LOCATION: Bath A Master Bathroom B Main C Great Room D E

72 Toilet N/A **Appears serviceable** A B C D E

Toilet loose at floor*	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E	Loose toilet tank*	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E
Recommend new wax seal (2)	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E	Cracked Tank *	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E
Water runs continually in tank*	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E	Rust in Tank *	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E
Does not flush properly*	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E	Moisture around toilet (2)	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E

Comments:

73 Sink N/A **Appears serviceable** A B C D E Hot & cold water reversed*(4)

Sink cracked*	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E	Corrosion under sink*	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E
Faucet appears serviceable	<input checked="" type="checkbox"/> A <input checked="" type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E	Corrosion at sink faucet*	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E
Sink faucet leaks*	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E	Corrosion on supply valve below sink*	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E
Low water volume*	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E	Sink drain stopper non-functional / missing*	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E
Drain appears serviceable	<input checked="" type="checkbox"/> A <input checked="" type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E	Improper drain trap (2)	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E
Slow draining*	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E	Restricted view below sink*	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E
Rust / corroded drain line*	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E	Deterioration to cabinet*	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E
Leaking drain line (2)	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E	Moisture damage below sink*	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E
Counter & cabinet			
Appears serviceable	<input checked="" type="checkbox"/> A <input checked="" type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E		
Damage to counter*	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E		
Grout needed at counter*	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E		

Comments:

74 Vent / Heat N/A **Appears serviceable** A B C D E

Comments:

75 Bathtub N/A **Appears serviceable** A B C D E

Damage to tub*	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E	Not applicable to this bathroom	<input checked="" type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E
Faucet appears serviceable	<input type="checkbox"/> A <input checked="" type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E	Whirlpool not functional (2)	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E
Hot & Cold water reversed(4)	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E	Whirlpool not tested(2)	<input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E
Damage at faucet*	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E	Drain stopper missing*	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E
Drain appears serviceable	<input type="checkbox"/> A <input checked="" type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E	Grout needed tub to wall*	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E
Slow draining at bathtub*	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E		

Comments:

76 Shower N/A **Appears serviceable** A B C D E

Damage to shower walls*	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E	Not applicable to this bathroom	<input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E
Grout needed at shower walls*	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E	Cracked tile(s)*	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E
Moisture damage to wall (2)(3)	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E	Caulking needed at floor*	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E
Slow draining at shower	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E	Floor needs caulking*	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E
Leaking at water valve(s) (2)	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E	Low water volume at shower(2)	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E
Shower head drip(2)	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E	Shower diverter non-functional(2)	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E
Enclosure appears serviceable	<input checked="" type="checkbox"/> A <input checked="" type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E	Unable to determine if glass is tempered*	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E
Glass does not appear to be tempered*	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E	Not applicable to this bathroom	<input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E
Broken glass*	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E	Corroded fixtures*	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E
Caulking needed at enclosure*	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E	Doors difficulty to operate*	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E
		Damaged enclosure*	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E

Comments:

Notice: Determining whether shower pans are watertight is beyond the scope of this inspection.*